## PUBLIC WORKS DEPARTMENT

From

Er M.Muthamilselvi, B.E., Superintending Engineer, PWD Buildings Construction and Maintenance Circle, Thanjavur-1 To

The Correspondent, Sivasakthi International School (CBSE) No.1/1, china Salai, S.f.No.16/2A,13 A2, Thalanayar, Vedaranyam Taluk, Nagapattinam District

Letter No

F-13 /DB/JDO-1/2022/ Dated 02.05.2022

Sir.

Sub: Buildings – Sivasakthi International School (CBSE), No.1/1, Chinna Salai, S.F.No. 16/2A,13A2, Thalanayar in Vedaranyam Taluk, in Nagapattinam District. – Structural stability Certificate – Prior Approval accorded – Regarding.

Ref : 1.G.O.Ms.No.231/Municipal Administration and water supply Department, Dated:24.09.1996 .

- The Correspondent , Sivasakthi International School (CBSE),
   No.1/1, Chinna Salai, S.F.No. 16/2A,13A2, Thalanayar in
   Vedaranyam Taluk, in Nagapattinam District, letter No.Nil dated nil
- Chief Engineer, (Buildings) PWD, Trichy Region, Trichy.
   Lr.No. AEE T2/F-Stability/2022/Dated:04.04.2022

With reference to the above 3<sup>rd</sup> letter cited. I enclose herewith the structural stability certificate for the School building of Sivasakthi International School (CBSE), No.1/1, Chinna Salai, S.F.No. 16/2A, 13 A2, Thalanayar in Vedaranyam Taluk, in Nagapattinam District for taking further action

Encl: Structural Stability Certificate -1 No

Superintending Engineer., P.W.D Buildings(C&M)Circle, Thanjavur-1.

6m/5/22

## FORM E

Form of report to be made to the competent Authority by inspecting authorities or officers appointed under section 28 of the Madras Public (Licensing) Act 1965 (Madras Act 13 of 1965) referred in rule 7 of the Madras Public Buildings (Licensing) Rule 1966

1	Name of the Designation of Inspecting authority or officer appointed or having jurisdiction under any other act of Law	Er M.Muthamilselvi, B.E., Superintending Engineer, PWD Buildings Construction and Maintenance Circle, Thanjavur-1
2	Location of the building inspected (Door No, Street No, Name of Place i.e Municipal corporation / Municipality / Panchayat or Panchayat Union / Township / Cantonment	Sivasakthi International School S.F.No.16/2A,13A2 at Thalanayar Town panchayat and village Vedaranyam Taluk,in Nagapattinam District
3	Date of Inspection	1) 25.10.2021 2) 02.05.2022
4	Purpose for which the building is used	Education (School Building)
5	Nature of defects noticed	NIL
6	Suggestions for rectifying defects	NIL
7	If in a dangerous condition immediate steps recommended to be taken	NIL

Superintending Engineer., P.W.D Buildings(C&M)Circle, Thanjavur -1. Form of opinion under sub section (1) of section 5 of the Madras Public Building (Licensing) Act 1965 (Madras Act 13 of the 1965 referred to in rule 5 of the Madras Public buildings (Licensing) Rules 1966)

\*\*\*\*\*\*

I have inspected the building specified in the statement below and I have satisfied myself that the building is structurally sound to be used as a Public Building for the purpose specified in the statement subject to the following conditions.

- The building is designed for GF+2 Floors and Ground floor and first floor has been completed.
- The structural stability of the structure has been assessed based on the structural designs, foundation details and soil report produced by the owner of the building.

The structural soundness of the building has been verified based on the structural design given by the private chartered Engineer and loading conditions as per the latest Indian Standards 875. I am therefore of the opinion that a license may be granted for the period from 01.11 .2021 to 31.10 .2024

Date of Inspection: 1) 25.10.2021

2) 02.05.2022

Superintending Engineer., P.W.D.

Buildings(C&M)Circle, Thanjavur-1

## OFFICE OF THE SUPERINTENDING ENGINEER, PWD,

# BUILDINGS CONSTRUCTION AND MAINTENANCE CIRCLE, TRICHY

(Form of opinion under sub-section (1) of section 28 of the Madras Public Building (Licensing) ACT 1965 (Madras ACT 13 of the 1965 referred to in rule 7 of the Madras Public building (Licensing) Rules 1966)

been enclosed herewith for reference. Assuming the building has been constructed as per the structural design furnished by the above private charted engineer Er.P. Rajamohan, M.Tech., P.R. Consultants (Structural consultant) as per the NOC issued by him which has private charted engineer, I have come to an opinion that the building is structurally sound to be used as a public Building for the I have inspected the building specified in the statement below. This building has been constructed under the supervision of the purpose specified in the statement. The structural soundness of the building has been verified taking into account the loading as per the latest Indian Standards 875. I am therefore of the opinion that a license may be granted for the period from 01.11.2021

Location of the Building (Door No. Street	Age of the	Purpose for	The Period for which	Number of persons to	
No. name of the Place	Building	which the building can be used	the building will be structurally sound	be accommodated	Remarks
Sivasakthi International School S.F.No.16/2A,13A2 at Thalanayar ,Vedaranyam Taluk,in Nagapattinam District Class Room Building: Ground floor 2750.46 Sq.m First floor 2750.46 Sq.m Head Room 2750.45 Sq.m	2 Years	Education ( School Building)	01.11.2021 to 31.10.2024	750 Nos	The building is structurally sound and stability ensured. In future stability can be assured if it will be maintained properly
24.31 Sq.m					

Superintending Engineer., P.W.D Buildings(C&M)Circle, Thanjavur -1.

11/2/2018